

Mailing Address:  
P.O. Box 2160  
Brighton, MI 48116-2160800 395-ASTI  
Fax: 810.225.3800[www.asti-env.com](http://www.asti-env.com)

November 4, 2015

Mr. Chris Miller  
**City of Adrian**  
135 East Maumee Street  
Adrian, Michigan 49221*RE: Asbestos Sampling of Debris Piles, 1365 Beecher Street, Adrian, Michigan  
(ASTI Project No. 9408)*

Dear Mr. Miller:

ASTI Environmental (ASTI) was retained to evaluate the stock piled debris at the former Dura facility and collect discrete samples from the debris for asbestos testing. ASTI observed three debris piles on the Property. Refer to attached figure for an approximate location and volume of the debris piles observed. Refer to Attachment A for photographs of the debris piles sampled. For this evaluation, ASTI visually evaluated building materials within the piles and collected samples to identify the presence and condition of any potential asbestos-containing materials (ACMs). Visual evaluation of the debris piles revealed each of the materials sampled, as well as the other debris present, were generally in poor condition and appear to have been exposed to the elements for an extensive period of time.

During the evaluation, ASTI personnel collected a total of 19 samples for asbestos testing. Samples were collected in accordance with applicable local, state and federal regulations. The samples were collected by Robert C. Anderson, PG, EP, State of Michigan Certified Asbestos Building Inspector (Accreditation No. A22206). Mr. Anderson's resume and accreditation are provided as Attachment B.

Following collection, the bulk samples were transmitted under chain-of-custody protocol to SanAir Technologies Laboratory, Inc. (SanAir) in Powhatan, Virginia for asbestos analysis using polarized light microscopy with dispersion staining (PLM/DS) in accordance with the US Environmental Protection Agency's (US EPA's) "Interim Method for the Determination of Asbestos in Bulk Building Materials" (EPA 600/R-93/116), December 1993).

The following material types were identified within the debris piles and sampled during the evaluation:

- Transite paneling
- Pipe insulation
- Roofing materials
- Various surfacing materials
- Various flooring materials and associated mastics
- Various floor tiles and associated mastics

On November 3, 2015 ASTI received the asbestos test results. Refer to Attachment C for a copy of the laboratory test results. Review of the results revealed the following materials were identified to contain asbestos:

SAMPLE ID	LOCATION	MATERIAL DESCRIPTION	RESULTS
PS-1	Pile No. 1	Roofing Material	5% Chrysotile
PS-2	Pile No. 1	Surfacing Material	20% Chrysotile
PS-4	Pile No. 1	Pipe Insulation	65% Chrysotile
PS-7	Pile No. 1	Transite	20% Chrysotile
PS-11	Pile No.1	Pipe Insulation	65% Chrysotile
PS-12	Pile No. 1	Pipe Insulation	70% Chrysotile
PS-14	Pile No. 2	Transite Mastic	20% Chrysotile 2% Chrysotile
PS-17	Pile No. 3	Roof Paper	5% Chrysotile
PS-18	Pile No. 3	Transite	20% Chrysotile
PS-19	Pile No. 3	Transite	20% Chrysotile

Review of the asbestos sample results revealed the identification of asbestos in each of the three debris piles. Accordingly, ASTI recommends that the debris be handled as friable asbestos-contaminated waste and care should be rendered to minimize disturbance of the material and the resulting potential release of asbestos fibers, including controlling fugitive dust. According to classification guidelines set forth in NESHAP, the pipe insulation and surfacing material are regulated materials, therefore these materials must be addressed by a licensed abatement contractor using Class I removal techniques and engineering controls to control dust.

If you have any questions regarding the contents and/or conclusions in this report, please do not hesitate to call ASTI at (800) 395-2784.

Sincerely,

**ASTI ENVIRONMENTAL**




Robert C. Anderson, PG, EP  
Asbestos Inspector No. A22206

Figure – Site Features Map

Attachments

- A Photo Log
- B Resume and Accreditation of Mr. Anderson
- C Results of Sample Analysis and Chain of Custody Document



- LEGEND**
-  Property Line
  -  Pole-Mounted Transformer
  -  Dumpster

# Former Dura Site

Created for: City of Adrian

ASTI Project No.: 9408, BJE, November 5, 2015

Adrian, MI

**Attachment A**  
**Photographs**

# PHOTO LOG

Former Dura Site, 1365 East Beecher Street, Adrian, Michigan



**Photo 1.** General view of stockpiled debris located on the south portion of the Property



**Photo 2.** General view of stockpiled debris located on the south portion of the Property



**Photo 3.** Close-up view of stockpiled debris on south portion of Property. Note pipe insulation in central portion of photograph.

## PHOTO LOG

Former Dura Site, 1365 East Beecher Street, Adrian, Michigan



**Photo 4.** General view of pipe wrap on original pipe collected from southern debris pile.



**Photo 5.** General view of stockpiled debris located on the western portion of the Property



**Photo 6.** General view of floor tile material and mastic observed in western debris pile

# PHOTO LOG

Former Dura Site, 1365 East Beecher Street, Adrian, Michigan



**Photo 7.** General view of surfacing material found in western debris pile



**Photo 8.** General view of floor tile in western debris pile

**Attachment B**

**Credentials of Robert C. Anderson, PG, EP  
State of Michigan Asbestos Inspector  
Accreditation Number A22206**

# RESUME

ASTI ENVIRONMENTAL



**ROBERT C. ANDERSON, P.G.**  
Director – Site Redevelopment Services

---

## PROFILE

### Certifications/Licenses

Environmental Professional (AAI)  
OSHA 29 CFR 1910.120 HAZWOPER  
OSHA 29 CFR 1910.120 HAZWOPER – Recertification (2014)  
Certified State of Michigan Lead Inspector and Lead Risk Assessor (P-05969)  
Asbestos Building Inspector Certificate (Certification No. 1063)  
Certified UST Professional – Michigan (Certification No. 584)  
Certified Industrial Storm Water Operator (Certification No. 09370)  
Certified Construction Site Storm Water Operator (Certification No. 10574)  
Licensed Geologist – Indiana (License No. IN2156)  
ASTM Risk-Based Corrective Action Applied to Petroleum Sites  
Certified Radon Measurement Specialist (Certification No. NRSB13SS043)

### Education

Old Dominion University (Graduate Studies - Geophysics) 1984 - 1986  
Lake Superior State College, B.S., Geology, 1983

### Experience History

Director - Site Redevelopment Services, ASTI ENVIRONMENTAL  
Vice-President – Environmental Services, Yeoman Group  
Team Leader – Atwell-Hicks, LLC  
Director – Environmental Services, CTI and Associates

### Professional Memberships and Service

Michigan Association of Environmental Professionals

### Professional Background

Mr. Anderson has more than 25 years experience in the environmental industry including environmental due diligence, due care evaluation and planning, soil/groundwater investigation and remediation programs for the financial and legal clients. Mr. Anderson has also coordinated numerous hazardous material and pre-demolition surveys which included evaluations of lead-based paint, asbestos, mold and radon for commercial and residential developments. In addition, Mr. Anderson has developed and coordinated various MSHDA and HUD environmental submittals for multi-family residential developments including Phase I and II Environmental Site Assessments, Baseline Environmental Assessments and Due Care Plans, asbestos, lead-based paint and mold surveys and management programs.

### **Years Experience:**

2 --- ASTI Environmental

25 --- other firms

## **ENVIRONMENTAL DUE DILIGENCE AND SITE INVESTIGATION PROJECTS**

### Environmental Site Assessments

Investigator and project manager for numerous projects (vacant land, agricultural, residential, commercial, and industrial) to determine the environmental condition of sites for real estate transactions. Projects involved both surface and subsurface evaluations of the sites for hazardous substances and petroleum products. Responsibilities include the preparation and/or review of ASTM Phase I and Transaction Screen ESAs, Baseline Environmental Assessments (BEAs), and Due Care Plans. Mr. Anderson is also knowledgeable with All Appropriate Inquiries (AAI) per 40 CFR Part 312 and meets the requirements of an Environmental Professional per AAI.

### Site Assessment of 26 Automobile Dealerships in Michigan and Florida

Project manager for environmental due diligence on transaction involving 26 automobile dealerships including completion of Phase I ESA, Phase II testing, as well as hazardous material survey. Audit included evaluation of facility compliance and cleaning and inspection of drainage structures. Project completed in 6 weeks and allowed client to close prior to end of year as required by the bank.

### Vapor Intrusion Evaluation, Flint, Michigan

Conducted multiple vapor intrusion studies at commercial properties to assess potential vapor migration. Scope of work included coordination of vapor intrusion points, vapor sample collection and coordination of chemical testing. Following receipt of the chemical test results, potential vapor intrusion issues were addressed.

## **ASBESTOS, LEAD-BASED PAINT AND HAZARDOUS MATERIALS SURVEYS**

Responsible for quality control and coordination of field activities for hazardous material survey, asbestos, lead-based paint and mold related testing. Acted as resource to staff regarding implementation of company's asbestos, lead-based paint, mold assessment program. In addition to the above, coordinated clearance sampling following lead dust hazard, following completion of lead, asbestos and mold remediation projects.

### Former Redford High School, Redford, Michigan

Project coordinator for asbestos abatement, hazardous material removal, hydraulic hoist and UST removal activities. Worked with on-site industrial hygienist to document asbestos abatement and demolition activities. Provided air

monitoring assistance during building demolition activities.

### Former LTV Steel Facility, Ferndale, Michigan

Project coordinator for environmental due diligence for property acquisition including completion of Phase I, Phase II, asbestos and hazardous material survey. Assisted certified building asbestos inspector with asbestos survey and quantification, as well as hazardous material survey.

### Former Brighton Athletic Center, Brighton, Michigan

Project coordinator for asbestos, hazardous material and lead inspection. Assisted certified building asbestos inspector with asbestos survey and quantification, as well as hazardous material survey. Coordinated with industrial hygienist during abatement and clearance sampling.

## **PETROLEUM REMEDIATION PROJECTS**

### Private Oil Company Divestiture

Project manager for major oil company divestiture for 42 petroleum service stations located in southeastern Michigan. Work included completion of Phase I and II site evaluations including review of tank monitoring data, review of historical corrective actions conducted on-site, and completion of soil and groundwater testing. Following completion of field studies cost-to-close evaluations were conducted at each location where release was identified. Work was completed with no delays or injuries

### Hoist Decommissioning Program – Automobile Dealership, Southeastern Michigan

Project manager for environmental due diligence and hoist decommissioning at a large automobile dealership. Work included completion of a Phase I ESA and Phase II testing, followed by the removal of 26 in-ground hydraulic hoists, one oil/water separator and approximately 1,200 cubic yards of petroleum impacted soil. Following soil removal soil verification samples were collected for chemical testing and the site was restored.

## **CONTACT INFORMATION**

Mr. Anderson can be reached at ASTI Environmental (ASTI), 10448 Citation Drive, Suite 100, Brighton, MI 48116, or by calling 810.225.2800 (Toll-Free 800.395.ASTI). His email address is randerson@asti-env.com. More information about ASTI is available on the web at [www.asti-env.com](http://www.asti-env.com).

*State of Michigan*  
Department of Licensing and Regulatory Affairs  
Michigan Occupational Safety & Health Administration - Asbestos Program

 **Asbestos Inspector**

**Robert C. Anderson**  
5066 Wishing Well Drive  
Grand Blanc, MI 48439



**Accreditation Number** **A22206** **Expiration Date** **09/23/2016**

 **DOB: 04/05/1959**

This individual has satisfactorily met or exceeded the requirements of Michigan Public Act 440 of 1988, as amended, to be accredited as an Asbestos Inspector.

Accreditation card is not valid if altered **118372**

**Attachment C**

**Laboratory Report and Chain of Custody Document**

# SanAir Technologies Laboratory

## Analysis Report prepared for ASTI Environmental

Report Date: 11/3/2015  
Project Name: Dura Site  
Assessment  
Project #: 9408  
SanAir ID#: 15034307



NVLAP LAB CODE 200870-0



Certification # 652931



License # LAB0166



804.897.1177

[www.sanair.com](http://www.sanair.com)



# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

ASTI Environmental  
10448 Citation Dr.  
Suite 100  
Brighton, MI 48116

November 3, 2015

SanAir ID # 15034307  
Project Name: Dura Site Assessment  
Project Number: 9408

Dear Robert Anderson,

We at SanAir would like to thank you for the work you recently submitted. The 19 sample(s) were received on Friday, October 30, 2015 via FedEx. The final report(s) is enclosed for the following sample(s): PS-1, PS-2, PS-3, PS-4, PS-5, PS-6, PS-7, PS-8, PS-9, PS-10, PS-11, PS-12, PS-13, PS-14, PS-15, PS-16, PS-17, PS-18, PS-19.

These results only pertain to this job and should not be used in the interpretation of any other job. This report is only complete in its entirety. Refer to the listing below of the pages included in a complete final report.

Sincerely,

Sandra Sobrino  
Asbestos & Materials Laboratory Manager  
SanAir Technologies Laboratory

Final Report Includes:

- Cover Letter
- Analysis Pages
- Disclaimers and Additional Information

sample conditions:

19 sample(s) in Good condition



# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

15034307

FINAL REPORT

**Name:** ASTI Environmental  
**Address:** 10448 Citation Dr.  
Suite 100  
Brighton, MI 48116

**Project Number:** 9408  
**P.O. Number:**  
**Project Name:** Dura Site Assessment

**Collected Date:** 10/27/2015  
**Received Date:** 10/30/2015 10:50:00 AM  
**Report Date:** 11/3/2015 4:24:48 PM  
**Analyst:** Sobrino, Sandra

## Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-1 / 15034307-001 Stockpiled Debris	Black Non-Fibrous Heterogeneous		95% Other	5% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-2 / 15034307-002 Stockpiled Debris	Grey Non-Fibrous Heterogeneous	25% Cellulose	55% Other	20% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-3 / 15034307-003 Stockpiled Debris	Brown Fibrous Heterogeneous	85% Cellulose	15% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-4 / 15034307-004 Stockpiled Debris	White Fibrous Homogeneous		35% Other	65% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-5 / 15034307-005 Stockpiled Debris, Plaster	White Non-Fibrous Heterogeneous		100% Other	None Detected
PS-5 / 15034307-005 Stockpiled Debris, Drywall	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-6 / 15034307-006 Stockpiled Debris, Flashing	Black Non-Fibrous Heterogeneous		100% Other	None Detected
PS-6 / 15034307-006 Stockpiled Debris, Felt	Black Fibrous Homogeneous	85% Cellulose	15% Other	None Detected

### Certification

Analyst: *Sandra Sobrino*  
Analysis Date: 11/3/2015

Approved Signatory: *[Signature]*  
Date: 11/3/2015



# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

15034307

FINAL REPORT

**Name:** ASTI Environmental  
**Address:** 10448 Citation Dr.  
Suite 100  
Brighton, MI 48116

**Project Number:** 9408  
**P.O. Number:**  
**Project Name:** Dura Site Assessment

**Collected Date:** 10/27/2015  
**Received Date:** 10/30/2015 10:50:00 AM  
**Report Date:** 11/3/2015 4:24:48 PM  
**Analyst:** Sobrino, Sandra

## Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-7 / 15034307-007 Stockpiled Debris	Grey Non-Fibrous Homogeneous	80%	Other	20% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-8 / 15034307-008 Stockpiled Debris, Insulation	Grey Fibrous Homogeneous	100% Cellulose	< 1% Other	None Detected
PS-8 / 15034307-008 Stockpiled Debris, Cover	White Non-Fibrous Homogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-9 / 15034307-009 Stockpiled Debris	Black Non-Fibrous Heterogeneous		100% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-10 / 15034307-010 Stockpiled Debris	Black Fibrous Homogeneous	85% Cellulose	15% Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-11 / 15034307-011 Stockpiled Debris	Grey Fibrous Homogeneous		35% Other	65% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-12 / 15034307-012 Stockpiled Debris	Grey Fibrous Homogeneous		30% Other	70% Chrysotile

### Certification

Analyst: *Sandra Sobrino*  
Analysis Date: 11/3/2015

Approved Signatory: *[Signature]*  
Date: 11/3/2015



# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

15034307

FINAL REPORT

**Name:** ASTI Environmental  
**Address:** 10448 Citation Dr.  
Suite 100  
Brighton, MI 48116

**Project Number:** 9408  
**P.O. Number:**  
**Project Name:** Dura Site Assessment

**Collected Date:** 10/27/2015  
**Received Date:** 10/30/2015 10:50:00 AM  
**Report Date:** 11/3/2015 4:24:48 PM  
**Analyst:** Sobrino, Sandra

## Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-13 / 15034307-013 Stockpiled Debris	White Non-Fibrous Heterogeneous	100%	Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-14 / 15034307-014 From Stockpile, Transite	Grey Non-Fibrous Homogeneous	80%	Other	20% Chrysotile
PS-14 / 15034307-014 From Stockpile, Adhesive	Black Non-Fibrous Homogeneous	98%	Other	2% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-15 / 15034307-015 FT And Mastic From Stockpile, Floor Tile	Brown Non-Fibrous Homogeneous	100%	Other	None Detected
PS-15 / 15034307-015 FT And Mastic From Stockpile, Mastic	Black Non-Fibrous Homogeneous	100%	Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-16 / 15034307-016 Stockpiled Debris, Paper	Brown Fibrous Homogeneous	100% Cellulose	< 1% Other	None Detected
PS-16 / 15034307-016 Stockpiled Debris, Plaster	White Non-Fibrous Heterogeneous	100%	Other	None Detected

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-17 / 15034307-017 Stockpiled Debris	Various Non-Fibrous Heterogeneous	45% Cellulose	50% Other	5% Chrysotile

### Certification

Analyst: *Sandra Sobrino*  
Analysis Date: 11/3/2015

Approved Signatory: *[Signature]*  
Date: 11/3/2015



# SanAir Technologies Laboratory, Inc.

1551 Oakbridge Drive, Suite B, Powhatan, VA 23139  
804.897.1177 Toll Free: 888.895.1177 Fax: 804.897.0070  
Web: <http://www.sanair.com> E-mail: [iaq@sanair.com](mailto:iaq@sanair.com)

SanAir ID Number

**15034307**

FINAL REPORT

**Name:** ASTI Environmental  
**Address:** 10448 Citation Dr.  
Suite 100  
Brighton, MI 48116

**Project Number:** 9408  
**P.O. Number:**  
**Project Name:** Dura Site Assessment

**Collected Date:** 10/27/2015  
**Received Date:** 10/30/2015 10:50:00 AM  
**Report Date:** 11/3/2015 4:24:48 PM  
**Analyst:** Sobrino, Sandra

## Asbestos Bulk PLM EPA 600/R-93/116

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-18 / 15034307-018 Stockpiled Debris	Grey Non-Fibrous Heterogeneous		80% Other	20% Chrysotile

SanAir ID / Description	Stereoscopic Appearance	Components		Asbestos Fibers
		% Fibrous	% Non-Fibrous	
PS-19 / 15034307-019 Stockpiled Debris, Transite	Grey Non-Fibrous Homogeneous		80% Other	20% Chrysotile
PS-19 / 15034307-019 Stockpiled Debris, Fiber Board	Brown Fibrous Homogeneous	98% Cellulose	2% Other	None Detected

### Certification

Analyst: *Sandra Sobrino*  
Analysis Date: 11/3/2015

Approved Signatory:

Date: 11/3/2015

## **Disclaimer**

The final report cannot be reproduced, except in full, without written authorization from SanAir. Fibers smaller than 5 microns cannot be seen with this method due to scope limitations. The accuracy of the results is dependent upon the client's sampling procedure and information provided to the laboratory by the client. SanAir assumes no responsibility for the sampling procedure and will provide evaluation reports based solely on the sample and information provided by the client. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

For NY state samples, method EPA 600/M4-82-020 is performed.

Polarized- light microscopy is not consistently reliable in detecting asbestos in floor covering and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing.

NY ELAP lab ID 11983



1551 Oakbridge Drive Suite B  
 Powhatan, VA 23139  
 804-897-1177 / 888-895-1177  
 Fax 804-897-0070  
 www.sanair.com

Asbestos  
 Chain of Custody

SanAir ID Number  
 15034307

Company: <b>ASTI Environmental</b>		Project #: <b>9408</b>	Collected by: <b>R. Anderson</b>
Address: <b>10448 Citation Drive</b>		Project Name: <b>Dura Site Assessment</b>	Phone #: <b>810.225.2800</b>
City, St., Zip: <b>Brighton, MI 48116</b>		Date Collected: <b>10/27/15</b>	Fax #: <b>810.225.3800</b>
State of Collection: <b>MI</b>	Account#:	P.O. Number:	Email: <b>RANDERSON@ASTI-ENV.COM</b>

Bulk		Air		Soil/Vermiculite	
ABB	PLM EPA 600/R-93/116 <input checked="" type="checkbox"/>	ABA	PCM NIOSH 7400 <input type="checkbox"/>	ABSE	PLM EPA 600/R-93/116 (Qual.) <input type="checkbox"/>
	Positive Stop <input type="checkbox"/>	ABA-2	OSHA w/ TWA* <input type="checkbox"/>	ABSP	PLM CARB 435 (LOD <1%) <input type="checkbox"/>
ABEPA	PLM EPA 400 Point Count <input type="checkbox"/>	ABTEM	TEM AHERA <input type="checkbox"/>	ABSP1	PLM CARB 435 (LOD 0.25%) <input type="checkbox"/>
ABB1K	PLM EPA 1000 Point Count <input type="checkbox"/>	ABATN	TEM NIOSH 7402 <input type="checkbox"/>	ABSP2	PLM CARB 435 (LOD 0.1%) <input type="checkbox"/>
ABBEN	PLM EPA NOB <input type="checkbox"/>	ABT2	TEM Level II <input type="checkbox"/>		
ABBCH	TEM Chatfield <input type="checkbox"/>				
ABBTM	TEM EPA NOB <input type="checkbox"/>				
Water		New York ELAP		Dust	
ABHE	EPA 100.2 <input type="checkbox"/>	PLM NY	PLM EPA 600/M4-82-020 <input type="checkbox"/>	ABWA	TEM Wipe ASTM D-6480 <input type="checkbox"/>
		ABEPA2	NY ELAP 198.1 <input type="checkbox"/>	ABDMV	TEM Microvac ASTM D-5755 <input type="checkbox"/>
		ABENY	NY ELAP 198.6 PLM NOB <input type="checkbox"/>	Matrix	Other <input type="checkbox"/>
		ABBNY	NY ELAP 198.4 TEM NOB <input type="checkbox"/>		

Turn Around Times	3 HR (4 HR TEM) <input type="checkbox"/>	6 HR (8HR TEM) <input type="checkbox"/>	12 HR <input type="checkbox"/>	24 HR <input type="checkbox"/>
	2 Days <input type="checkbox"/>	3 Days <input type="checkbox"/>	4 Days <input type="checkbox"/>	5 Days <input type="checkbox"/>

**Special Instructions**

Sample #	Sample Identification/Location	Volume or Area	Sample Type	Flow Rate*	Time* Start - Stop
PS-1	stack piled DEBRIS - BLACK				
PS-2	" " - Grey				
PS-3	" " - BROWN				
PS-4	" " - Grey				
PS-5	" " - Grey/Brown				
PS-6	" " - BLACK				
PS-7	" " - Grey/BLACK				
PS-8	" " - White				
PS-9	" " - BLACK				
PS-10	" " - Black/Brown				
PS-11	" " - Grey				
PS-12	" " - Grey				

Relinquished by	Date	Time	Received by	Date	Time
R. Anderson	10/29/15	2:30 PM	[Signature]	OCT 30 2015	10:50 AM

Unless scheduled, the turn around time for all samples received after 3 pm EST Friday will begin at 8 am Monday morning. Weekend or Holiday work must be scheduled ahead of time and is charged for rush turn around time. Work with standard turn around time sent Priority Overnight and Billed to Recipient will be charged a \$10 shipping fee.

